HPO File No. 2022_0263

ITEM B6 1115 E 14th St Norhill

CERTIFICATE OF APPROPRIATENESS

Application Date: October 28, 2022

Applicant: Lola Clemmer, agent for, William Crenshaw, owner

Property: 1115 E 14th Street, Lot 17, Block 117, Norhill Neighborhood Subdivision.

The property includes a historic 1,140 square foot, one-story wood single-family residence situated on a 5,000 square foot (50' x 100') interior lot.

Significance: Contributing Bungalow style residence, constructed circa 1925, located in

the Norhill Historic District.

Proposal: Alteration: Windows

Replace all 15 original, wood windows on structure

Replace with 1-over-1, double-hung, inset & recessed, Fibrex windows

Public Comment: No public comment received.

Civic Association: No comment received.

Recommendation: Approval with conditions: Replace windows numbered 101-104 and 114-115 (those

on the rear of the structure and the two windows on the NE rear corner of structure).

Retain all other original windows.

HAHC Action: -

ITEM B6 1115 E 14th St Norhill

APPROVAL CRITERIA

ALTERATIONS, REHABILITATIONS, RESTORATIONS AND ADDITIONS

Sec. 33-241: HAHC shall issue a certificate of appropriateness for the alteration, rehabilitation, restoration or addition of an exterior feature of (i) any landmark, (ii) protected landmark, (iii) any building, structure or object that is part of an archaeological site, or (iv) contributing building in a historic district upon finding that the application satisfies the following criteria, as applicable:

S	D	NA		S - satisfies D - does not satisfy NA - not applicable
\boxtimes			(1)	The proposed activity must retain and preserve the historical character of the property;
\boxtimes			(2)	The proposed activity must contribute to the continued availability of the property for a contemporary use;
\boxtimes			(3)	The proposed activity must recognize the building, structure, object or site as a product of its own time and avoid alterations that seek to create an earlier or later appearance;
			(4)	The proposed activity must preserve the distinguishing qualities or character of the building, structure, object or site and its environment; Many of the original wood, 1-over-1 windows visible from the public right-of-way are in repairable condition.
\boxtimes			(5)	The proposed activity must maintain or replicate distinctive stylistic exterior features or examples of skilled craftsmanship that characterize the building, structure, object or site;
			(6)	New materials to be used for any exterior feature excluding what is visible from public alleys must be visually compatible with, but not necessarily the same as, the materials being replaced in form, design, texture, dimension and scale;
			(7)	The proposed replacement of exterior features, if any, should be based on an accurate duplication of features, substantiated by available historical, physical or pictorial evidence, where that evidence is available, rather than on conjectural designs or the availability of different architectural elements from other structures;
			(8)	Proposed additions or alterations must be done in a manner that, if removed in the future, would leave unimpaired the essential form and integrity of the building, structure, object or site; To remove all original wood, 1-over-1 windows visible from the public right-of-way would have an adverse impact on the character of the structure.
			(9)	The proposed design for any exterior alterations or addition must not destroy significant historical, architectural, archaeological or cultural material, including but not limited to siding, windows, doors and porch elements; To remove all original wood, 1-over-1 windows visible from the public right-of-way would have an adverse impact on the character of the structure.
			(10)	The proposed alteration or addition must be compatible with the massing, size, scale material and character of the property and the context area; and To replace all original wood windows would have an adverse impact on the character of the property.
			(11)	The distance from the property line to the front and side walls, porches, and exterior features of any proposed addition or alteration must be compatible with the distance to the property line of similar elements of existing contributing structures in the context area.

1115 E 14th St Norhill

District Map




1115 E 14th St Norhill

Current Photo



1115 E 14th St Norhill

Window Floor Plan Map



1115 E 14th St Norhill

Photos Provided by Agent



Photos Provided by Agent



Photos Provided by Agent





1115 E 14th St Norhill

Photos Provided by Staff #s 105 & 106




Windows 105-106 are in repairable condition


Norhill

December 14, 2022 HPO File No. 2022_0263

Photos Provided by Agent



Photos Provided by Agent



108

Ordinance does not cover interior repair work

Photos Provided by Staff #s 107 & 108





Windows 107-108 are in repairable condition

107

108









1115 E 14th St Norhill

Photos Provided by Agent



109



110



Ordinance does not cover interior repair work

1115 E 14th St Norhill

Photos Provided by Staff #s 109 & 110















Windows
109-110
are in
repairable
condition

1115 E 14th St Norhill

Photos Provided by Agent



Photos Provided by Agent







Photos Provided by Staff #s 111 & 112









Windows 111 & 112 are in repairable condition



Photos Provided by Staff #113





Window 113 is in repairable condition