1022 Peddie St Norhill

CERTIFICATE OF APPROPRIATENESS

Applicant: Adam Till, owner / Yvette Solares, agent

Property: 1022 Peddie St, lot 6, block 110 in the Norhill Subdivision. The property includes a historic 1,334

square-foot, one-story wood-frame single-family residence, situated on a 5,000 square foot (50' x

100') interior lot.

Significance: Contributing Bungalow residence, constructed circa 1930, located in the Norhill Historic District.

Proposal: Alteration – Windows:

The applicant proposes to replace the original 1/1 wood windows with Renewal by Andersen Fibrex

windows.

Changes include:

Removal of 18 existing original wood windows

Installation of 18 Renewal by Andersen fibrex windows

See enclosed detailed project description and application materials for further details.

Public Comment: No public comment received.

Civic Association: No comment received.

Recommendation: Denial

HAHC Action: -

1022 Peddie St Norhill

APPROVAL CRITERIA

ALTERATIONS, REHABILITATIONS, RESTORATIONS AND ADDITIONS

Sec. 33-241: HAHC shall issue a certificate of appropriateness for the alteration, rehabilitation, restoration or addition of an exterior feature of (i) any landmark, (ii) protected landmark, (iii) any building, structure or object that is part of an archaeological site, or (iv) contributing building in a historic district upon finding that the application satisfies the following criteria, as applicable:


S	D	NA		S - satisfies D - does not satisfy NA - not applicable
			(1)	The proposed activity must retain and preserve the historical character of the property; The existing windows are in need of repair, thus preserving the character of the property.
			(2)	The proposed activity must contribute to the continued availability of the property for a contemporary use;
			(3)	The proposed activity must recognize the building, structure, object or site as a product of its own time and avoid alterations that seek to create an earlier or later appearance;
			(4)	The proposed activity must preserve the distinguishing qualities or character of the building, structure, object or site and its environment; By replacing windows that are in good condition, the windows are not being preserved.
			(5)	The proposed activity must maintain or replicate distinctive stylistic exterior features or examples of skilled craftsmanship that characterize the building, structure, object or site;
			(6)	New materials to be used for any exterior feature excluding what is visible from public alleys must be visually compatible with, but not necessarily the same as, the materials being replaced in form, design, texture, dimension and scale;
			(7)	The proposed replacement of exterior features, if any, should be based on an accurate duplication of features, substantiated by available historical, physical or pictorial evidence, where that evidence is available, rather than on conjectural designs or the availability of different architectural elements from other structures;
			(8)	Proposed additions or alterations must be done in a manner that, if removed in the future, would leave unimpaired the essential form and integrity of the building, structure, object or site;
			(9)	The proposed design for any exterior alterations or addition must not destroy significant historical, architectural, archaeological or cultural material, including but not limited to siding, windows, doors and porch elements; By removing the existing windows, would indeed be destroying significant historic material
\boxtimes			(10)	The proposed alteration or addition must be compatible with the massing, size, scale material and character of the property and the context area; and
			(11)	The distance from the property line to the front and side walls, porches, and exterior features of any proposed addition or alteration must be compatible with the distance to the property line of similar elements of existing contributing structures in the context area.
				OLD SIXTH WARD DESIGN GUIDELINES
				In accordance with Sec. 33-276, the proposed activity must comply with the City Council approved Design Guidelines.

PROPERTY LOCATION

NORHILL HISTORIC DISTRICT



Building Classification



Norhill

INVENTORY PHOTO



INVENTORY PHOTO



Norhill

EXISTING WINDOWS



Image 1



Image 4



Image 2




Image 5



Image 3



Image 6



ATTACHMENT A:

PHOTOS

















CERTIFICATE OF APPROPRIATENESS



222<u>7493</u> TILL

EXISTING WINDOW SCHEDULE									
Window	Material	Lite Pattern	Style	Dimensions	Recessed/Inset	Original/ Replacement	Existing to Remain		
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Original	No		
101	Wood	1/1	DH	30×57	Recessed	Original	NO		
102	11	1/1	DH	30 ×57	Recessed	Original	NO		
103	11	1/1	DH	30×57	Recessed	Original	NO		
104	11	1/)	DH	30×57	Recessed	Original	NO		
105	(1	1/1	DH	30×57	Recessed	Original	NO		
106	11	1/1	DH	30×57	Recessed	Original	NO		
107	Aluminum	1/2	DH	36 + 39	Recessed	Replacement	NO		
108	11	1/1	DH	30 × 57	Recessed.	Original	NO		
109	11	1/1	DH	30 × 57	Recessed	Occainal	NO		

WINDOW WORKSHEET

	DAMAGE TO EXISTING WINDOWS
Window	Describe Damage
Ex. A1	Glass is broke, window is inoperable, rail is rotten, and frame is broken
101	Wood Rot
102	Missing sash colds
103	Wood Rot
104	Wood Rot
105	Missing sash cords
106	Missing Hardware / Wood Rot
107	Broken pane (glass), window well not open
108	Wood Rot
109	Broken glass

PROPOSED WINDOW SCHEDULE							
Window	Material	Lite Pattern	Style	Dimensions	Recessed/ Inset	Brand/ Vendor	Other
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Plygem	
101	Fibrex	1/1	DH	30×57	Inset	Andersen	
102	11	/1	11	30×57	11	11	
103	11	/1	tf	30×57	21	41	
104	11	11	η	30×57	11	+1	
103	11	10	11	30×57	- is	11	
106	11	11	11	30 ×57	11	1s	
107	/1	[1	11	36×39	(1	71	
108	11	11	11	30×57	14	11	
109	(1	11	11	30×57	11	1)	

Must include photos of all windows with labels indicated on this sheet

Must include manufacture's specifications and details for all proposed windows

^{***} Use additional sheets as necessary

CERTIFICATE OF APPROPRIATENESS



2227793 TILL

EXISTING WINDOW SCHEDULE Window Material Lite Style Dimensions Recessed/Inset Original/ **Existing to** Pattern Replacement Remain Ex. Al Wood 1/1 DH 32 x 66 Recessed Original 110 WOOD 1/ DH 23 x57 RECESSED ORIGINAL NO 1/1 11 23x57 11 11 1/2 " 11 11 11 30 X57 " 113 11 11 11 30 X57 11 11 11 114 11 11 11 30 X57 li " 30 x57 11 115 11 11 11 11 1. 11 11 116 30 x57 11 11 11 " 117 11 11 30 157 11 11 11 118 11 11 11 11 11 23 x 33 11

WINDOW WORKSHEET

DAMAGE TO EXISTING WINDOWS							
Window	Describe Damage						
Ex. Al	Glass is broke, window is inoperable, rail is ratten, and frame is broken.	-					
110	Missing sash cords						
111	Wood Rot						
/12	Missing sesh cord						
H3	Missing sash cord						
174	Frame Damaged						
115	Missing sash cord						
116	Broken glass						
117	Wood RET						
118	Wood Damage						

Window	Material	Lite Pattern	Style	Dimensions	Recessed/ Inset	Brand/ Vendor	Other
110	FIAREX	1/1	PH	23 x.57	INSET	ANDERSEN	
111	11	/'	11	23 X57	1.	(1	
112	11	11	11	30 x57	"	"	
113	11	11	11	30 x57	4	(/	
114	11	11	11	30 157	11	11	
115	11	11	11	30 x57	0	11	
116	11	11	(1	30 K57	11	1/	
117	11	11	11	30 x 57	11	17	
118	1/	11	(1	10 ×57	/1	11	

Must include photos of all windows with labels indicated on this sheet

Must include manufacture's specifications and details for all proposed windows

^{***} Use additional sheets as necessary

Norhill

Double-

This classic window style is an excellent choice no matter where you live. Choose gently curved Contemporary or squared Traditional Check Rails.

CONVENIENT

Easy cleaning from the inside.

ELEGANT

Traditional look of mortise-andtenon styling.

ACCURATE

Appropriate for restoration and renovation projects.



Double-Hung Window



Double-Hung Cottage Style Window



Double-Hung Oriel Style Window










Traditional











Double-Hung Windows / White / Colonial Brille's



Choosing Renewal by Andersen Windows is Easy...

The Renewal by Andersen process starts with our consultative sales approach.

Our experienced sales representatives will work with you to find solutions to
enhance your home's functionality, energy efficiency and beauty.

