CERTIFICATE OF APPROPRIATENESS

Application Date: March 30, 2023

Applicant: Bernard Cisneros, agent for, Mary Cisneros, owner

Property: 7523 Rockhill Street, Lot 30, Block 67, Glenbrook Valley Sec. 7 Extn

Neighborhood Subdivision. The property includes a historic 1,867 square foot, one-story brick veneer single-family residence and attached garage

situated on a 8,625 square foot (75' x 115') interior lot.

Significance: Non-contributing Traditional Ranch style residence, constructed circa

1962, located in the Glenbrook Historic District.

Proposal: Alteration: Windows

Replace original aluminum windows with vinyl windows, double-hung, inset & recessed

- There is no damage to existing windows per window worksheet
- Reason for replacement: wanting energy efficiency per window
- As of April 10, 2023, vinyl windows have been installed and original, aluminum windows have been removed.

Public Comment: No public comment received.

Civic Association: No comment received.

Recommendation: Denial - does not satisfy criteriaDenial of COA. Issuance of COR for work completed and

the condition that surface mounted muntins of same shape be placed on the four windows

on front elevation where the diamond pattern simulated divided lite pattern appears.

HAHC Action: -

ITEM B08 7523 Rockhill St Glenbrook Valley

May 18, 2023 HPO File No. 2023_0069

APPROVAL CRITERIA

ALTERATIONS TO NONCONTRIBUTING STRUCTURES

Sec. 33-241.1(b): Director shall issue a certificate of appropriateness for the alteration, rehabilitation, or restoration of a non-contributing structure or an addition to a noncontributing structure in an historic district upon finding that the application satisfies the following criteria, as applicable:


S	D	NA		S - satisfies	D - does not satisfy	NA - not applicable
			(1)	For an alteration, rehabilitation, or restoration that does structural elements, not including the foundation, within		
				(a) The proposed activity must recognize the building, stime and avoid alterations that seek to create an earlier. The replacement of original aluminum windows with voriteria for matching the architectural features, materials structure and the contributing structures within the contributions.	or later appearance; a rinyl windows does not a, and character of the e	and satisfy the applicable
				(b) The proposed activity must match the architectural for existing noncontributing structure or the contributing structure architectural for matching the architectural features, materials structure and the contributing structures within the contributing structures within the contributions.	ructures within the cont rinyl windows does not , and character of the e	ext area. satisfy the applicable
			(2)	For an alteration, rehabilitation, or restoration that restructural elements, not including the foundation, with director shall refer the application to the HAHC, which if the result of the project conforms to the requirement section 33-242 of this Code.	nin 67 percent or more shall approve a certific	e of the structure, the ate of appropriateness
				ADMINISTRATIVE APPROVA	ALS	
find con to t	s that structions his s	at the position in subsect	oropo this a tion d	ne director is authorized to issue a certificate of appropriate sed activity will be performed in a manner that satisfies article, as applicable. If the director finds that an application oes not satisfy the applicable criteria, or that the applicable, the director shall refer the application to the HAHC for	s the criteria for alterati on for a certificate of apparation does not satisfy	ons, additions, or new propriateness pursuant
A		NA			A - applies	NA - not applicable
				Sec. 33-241.1(e) If the director does not approve the appursuant to this section within 15 business days of recesshall refer the application to the HAHC for consideration according to the criteria for alterations, additions, or new otherwise provided by this section. The schedule for confappropriateness provided by section 33-239 of this Counter this section and the administrative process author required for consideration. The director may promulgate applications under this section. The replacement of original does not satisfy the applicable criteria for matching the character of the existing noncontributing structure and the area. This application will be reviewed by the HAHC.	eipt of a complete applin. The HAHC shall review construction, as application of an application of an application of an application of an application of shall apply to an application of shall not see rules for the receipt again aluminum window architectural features,	cation, the director ew the application licable, or as cation for a certificate application considered suspend any time and processing of s with vinyl windows materials, and

May 18, 2023 HPO File No. 2023_0069 **ITEM B08** 7523 Rockhill St Glenbrook Valley

ALTERATIONS, REHABILITATIONS, RESTORATIONS AND ADDITIONS

Sec. 33-241: HAHC shall issue a certificate of appropriateness for the alteration, rehabilitation, restoration or addition of an exterior feature of (i) any landmark, (ii) protected landmark, (iii) any building, structure or object that is part of an archaeological site, or (iv) contributing building in a historic district upon finding that the application satisfies the following criteria, as applicable:

S	D	NA		S - satisfies D - does not satisfy NA - not applicable
			(1)	The proposed activity must retain and preserve the historical character of the property; The replacement of original aluminum windows with vinyl windows does not satisfy the applicable criteria for matching the architectural features, materials, and character of the existing noncontributing structure and the contributing structures within the context area.
			(2)	The proposed activity must contribute to the continued availability of the property for a contemporary use;
			(3)	The proposed activity must recognize the building, structure, object or site as a product of its own time and avoid alterations that seek to create an earlier or later appearance;
			(4)	The proposed activity must preserve the distinguishing qualities or character of the building, structure, object or site and its environment; The replacement of original aluminum windows with vinyl windows does not satisfy the applicable criteria for matching the architectural features, materials, and character of the existing noncontributing structure and the contributing structures within the context area.
	\boxtimes		(5)	The proposed activity must maintain or replicate distinctive stylistic exterior features or examples of skilled craftsmanship that characterize the building, structure, object or site;
			(6)	New materials to be used for any exterior feature excluding what is visible from public alleys must be visually compatible with, but not necessarily the same as, the materials being replaced in form, design, texture, dimension and scale; The simulated divided lite diamond pattern is incompatible with the 2-over-2 lite pattern of the aluminum windows in the context area.
			(7)	The proposed replacement of exterior features, if any, should be based on an accurate duplication of features, substantiated by available historical, physical or pictorial evidence, where that evidence is available, rather than on conjectural designs or the availability of different architectural elements from other structures;
\boxtimes			(8)	Proposed additions or alterations must be done in a manner that, if removed in the future, would leave unimpaired the essential form and integrity of the building, structure, object or site;
			(9)	The proposed design for any exterior alterations or addition must not destroy significant historical, architectural, archaeological or cultural material, including but not limited to siding, windows, doors and porch elements;
			(10)	The proposed alteration or addition must be compatible with the massing, size, scale material and character of the property and the context area; and Vinyl windows were never used in traditional ranch style structures and are therefore, incompatible to the character of the property and context area.
			(11)	The distance from the property line to the front and side walls, porches, and exterior features of any proposed addition or alteration must be compatible with the distance to the property line of similar elements of existing contributing structures in the context area.



7523 Rockhill St Glenbrook Valley

Window Worksheet

CERTIFICATE OF APPROPRIATENESS



WINDOW	WORKSHE	EET
--------	---------	-----

	EXISTING WINDOW SCHEDULE									
Window	Material	Lite Pattern	Style	Dimensions	Recessed/Inset	Original/ Replacement	Existing to Remain			
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Original	No			
AL	Alumino	m Diamon	SH	353/4 +71	3/4 Recessed	Original	No			
A2 A3	Alum-num		SH	353/4×713/4	Married Marrie	Oxiginal	No			
	Aluminur	/	SH	353/4×713/4	The second secon	Original	No			
A4	Alumi Aum	(, ,	SH	3534 +7134		Original	No			
A5	Aluminua	1/10	SH	353/4 x5(3)		Ovional	No			
ALC	Alyminus	3	SH	3534×513		Original	No			
A7	Alum nu		SH		K4 Recessed	Original	No			
AS	Aluminu	M S	SH	72×353/		Original	No			

DAMAGE TO EXISTING WINDOWS								
1								
flicient								
Hilient								

Window	Material	Lite Pattern	Style	Dimensions	Recessed/ Inset	Brand/ Vendor	Other
Ex. A1	Hagha	uality	DH	32 x 66	Recessed	Plygem	
Al	Vinyl	Diamond	DH	353/4×713/4	Recessed	Window Wor	Id (WW)
A2	Vinyl	Grid	DH	353/477134	Recessed	WW	
A3	Vinil	(DH	3534 471 34	Recessed	WW	
A4	Vinyl	Sho	DH	353/4×713/4		ww	
A4 A5	Vinyl	10	DH	353/4×5/34		WW	
AL	Vinyl	1/5	DH	3534x5134		WW	
AT	Vinyl	1	DH	2334+353	HRELESSED		
A8	Vinyl	01	DH	72×353/4	Recessed	WW	

- Must include photos of all windows with labels indicated on this sheet
- Must include manufacture's specifications and details for all proposed windows
- *** Use additional sheets as necessary

May 18, 2023 HPO File No. 2023_0069

Glenbrook Valley

Inventory Photo (4-9-2010)



Google Street View Photos (Jan. 2022)



Glenbrook Valley

May 18, 2023 HPO File No. 2023_0069

Google Street View Photos (Jan. 2022)





Current Photos Provided By Applicant – Front Elevation





Current Photos Provided By Applicant – Front Elevation





Current Photos Provided By Applicant – Right Elevation



Current Photos Provided By Applicant – Right Elevation





Current Photos Provided By Applicant – Right Elevation





Current Photos Provided By Staff





Current Photos Provided By Staff





7523 Rockhill St Glenbrook Valley

Current Photos Provided By Staff





Context Area of Contributing Structures





May 18, 2023 HPO File No. 2023_0069

Context Area of Contributing Structures







Context Area of Non-Contributing Structures



Context Area of Non-Contributing Structures







Context Area of Non-Contributing Structures







Glenbrook Valley

May 18, 2023 HPO File No. 2023_0069

Glenbrook Valley HD Inventory Lists of Context Area

6702 HOLLYGROVE	7 EXT	47	38	1965	Non-Contributing	Tudor Ranch	
6703 HOLLYGROVE	7 EXT	67	17	1964	Non-Contributing	Tudor Ranch	

25

CITY OF HOUSTON

Archaeological & Historical Commission

Planning and Development Department

SITE ADDRESS	SECTION	BLOCK	LOT	YEAR BUILT	STATUS	ARCHITECTURAL STYLE
6706 HOLLYGROVE	7 EXT	47	37A & 38A	1963	Non-Contributing	Traditional Ranch
6707 HOLLYGROVE	7 EXT	67	18	1964	Non-Contributing	Traditional Ranch
6710 HOLLYGROVE	7 EXT	47	36A & 37	1961	Non-Contributing	Traditional Ranch
6711 HOLLYGROVE	7 EXT	67	19	1963	Non-Contributing	Traditional Ranch
6714 HOLLYGROVE	7 EXT	47	36	1965	Non-Contributing	Traditional Ranch
6715 HOLLYGROVE	7 EXT	67	20	1965	Non-Contributing	Tudor Ranch
6722 HOLLYGROVE	7 EXT	47	35	1961	Non-Contributing	Traditional Ranch
6723 HOLLYGROVE	7 EXT	67	21	1964	Non-Contributing	Traditional Ranch
6726 HOLLYGROVE	7 EXT	47	34	1961	Non-Contributing	Traditional Ranch
6727 HOLLYGROVE	7 EXT	67	22	1964	Non-Contributing	Tudor Ranch
6730 HOLLYGROVE	7 EXT	47	33	1961	Contributing	Eclectic
6731 HOLLYGROVE	7 EXT	67	23	1964	Non-Contributing	Traditional Ranch
6734 HOLLYGROVE	7 EXT	47	32	1961	Non-Contributing	Tudor Ranch
6735 HOLLYGROVE	7 EXT	67	24	1964	Contributing	Modern Ranch
6738 HOLLYGROVE	7 EXT	47	31	1961	Non-Contributing	Tudor Ranch
6739 HOLLYGROVE	7 EXT	67	25	1964	Contributing	Modern Ranch
6742 HOLLYGROVE	7 EXT	47	30 & 31A	1961	Contributing	Tudor Ranch
6743 HOLLYGROVE	7 EXT	67	26	1964	Non-Contributing	Traditional Ranch
6746 HOLLYGROVE	7 EXT	47	29	1965	Non-Contributing	Tudor Ranch

May 18, 2023 HPO File No. 2023_0069 7523 Rockhill St Glenbrook Valley

Glenbrook Valley HD Inventory Lists of Context Area

7502 ROCKHILL	7 EXT	47	28	1961	Non-Contributing	Traditional Ranch
7506 ROCKHILL	7 EXT	47	27	1961	Non-Contributing	Traditional Ranch
7510 ROCKHILL	7 EXT	47	26	1962	Contributing	Modern Ranch
7511 ROCKHILL	7 EXT	67	27	1961	Non-Contributing	Traditional Ranch

29

CITY OF HOUSTON

Archaeological & Historical Commission

Planning and Development Department

SITE ADDRESS	SECTION	BLOCK	LOT	YEAR BUILT	STATUS	ARCHITECTURAL STYLE
7514 ROCKHILL	7 EXT	47	25	1962	Non-Contributing	Traditional Ranch
7515 ROCKHILL	7 EXT	67	28	1962	Non-Contributing	Traditional Ranch
7518 ROCKHILL	7 EXT	47	24	1962	Non-Contributing	Tudor Ranch
7519 ROCKHILL	7 EXT	67	29	1962	Non-Contributing	Traditional Ranch
7522 ROCKHILL	7 EXT	47	23	1962	Non-Contributing	Tudor Ranch
7523 ROCKHILL	7 EXT	67	30	1962	Non-Contributing	Traditional Ranch
7526 ROCKHILL	7 EXT	47	22	1962	Non-Contributing	Traditional Ranch
7527 ROCKHILL	7 EXT	67	31	1962	Non-Contributing	Traditional Ranch
7530 ROCKHILL	7 EXT	47	21	1962	Non-Contributing	Traditional Ranch
7531 ROCKHILL	7 EXT	67	32	1962	Non-Contributing	Tudor Ranch
7602 ROCKHILL	7 EXT	40	26	1965	Non-Contributing	Traditional Ranch
7606 ROCKHILL	7 EXT	40	27	1961	Non-Contributing	Traditional Ranch
7610 ROCKHILL	7 EXT	40	28	1962	Non-Contributing	Traditional Ranch