CERTIFICATE OF APPROPRIATENESS

Applicant: Ana S. Gamez agent for Jana Garza, owner

Property: 7954 Glenvista Street, Lot 14, Block 19, Section 4, Glenbrook Valley Sec. 4 Subdivision. The

property includes a one-story wood frame 1,645 square foot single-family residence situated on a

7,923 square foot corner lot.

Significance: Contributing Mid-Century Modern residence, constructed circa 1954, located in the Glenbrook

Valley Historic District.

Proposal: Alteration – Siding, windows, roof, porch

The applicant is proposing to maintain the complete unpermitted remodel of this structure.

Cementitious siding with 6" reveal

Maintaining of the current front facade

Maintaining of the current roof line

Maintaining of the removed garage that is currently a bedroom

Maintaining of the changed fenestrations including windows and doors

Public Comment:

Civic Association:

Recommendation: Denial of COA, issuance of COR

Reframe roof to original form

· Rebuild front elevation to match the original

HAHC Action:

7954 Glenvista St Glenbrook Valley

ALTERATIONS, REHABILITATIONS, RESTORATIONS AND ADDITIONS


Sec. 33-241: HAHC shall issue a certificate of appropriateness for the alteration, rehabilitation, restoration or addition of an exterior feature of (i) any landmark, (ii) protected landmark, (iii) any building, structure or object that is part of an archaeological site, or (iv) contributing building in a historic district upon finding that the application satisfies the following criteria, as applicable:

S	D	NA		S - satisfies D - does not satisfy NA -	not applicable
			(1)	The proposed activity must retain and preserve the historical character of the proper The completed work does not retain or preserve the historic character of the proper	
			(2)	The proposed activity must contribute to the continued availability of the property for use;	a contemporary
			(3)	The proposed activity must recognize the building, structure, object or site as a pro- time and avoid alterations that seek to create an earlier or later appearance; The completed work creates a later appearance and does not recognize it as a pro- in which it was built.	
			(4)	The proposed activity must preserve the distinguishing qualities or character structure, object or site and its environment; The completed work does not preserve the distinguishing qualities or character structure.	
			(5)	The proposed activity must maintain or replicate distinctive stylistic exterior features skilled craftsmanship that characterize the building, structure, object or site; The completed work does not maintain or replicate the exterior features that character structure.	•
			(6)	New materials to be used for any exterior feature excluding what is visible from pube visually compatible with, but not necessarily the same as, the materials being redesign, texture, dimension and scale; The completed work includes new materials that are not visually compatible.	
			(7)	The proposed replacement of exterior features, if any, should be based on an accurate of features, substantiated by available historical, physical or pictorial evidence, when is available, rather than on conjectural designs or the availability of different archite from other structures;	e that evidence
			(8)	Proposed additions or alterations must be done in a manner that, if removed in the leave unimpaired the essential form and integrity of the building, structure, object on The completed work would severely impair (and already has impaired) the form and structure.	site;
			(9)	The proposed design for any exterior alterations or addition must not destroy signi architectural, archaeological or cultural material, including but not limited to siding, and porch elements; The completed work destroyed the significant historical materials.	
\boxtimes			(10)	The proposed alteration or addition must be compatible with the massing, size, sca character of the property and the context area; and	ale material and
			(11)	The distance from the property line to the front and side walls, porches, and exterior proposed addition or alteration must be compatible with the distance to the proper elements of existing contributing structures in the context area.	



PROPERTY LOCATION

GLENBROOK VALLEY HISTORIC DISTRICT



12/6/2024

BLA PHOTO



INVENTORY PHOTO



CURRENT PHOTO



AERIAL VIEW OF PROPERTY



7954 Glenvista St Glenbrook Valley

BLA (1954)

		21449951		
	Harris C	2/44775/		
	BUILDING AS	SESSMENT		
	/ Houston.	Texas		
	Vol. 82 Page 303	0917		
	Vol. Page	Permit No. 97/		
	779	Inspector		
		10.19 51		
		Date 19 39		
	Owner			
	No. 1954 ylen Vista, sun			
	Survey or MO			
	Addition Henlinger			
	AbstLot or Tr	14 Blk 19		
	Type Residential			
	Industrial			
	Exterior: Permastone — Rock — Brick Veneer — Frame — Stucco —Concrete Tile — Claytile —			
	Cedar Shakes—Composition—Shingle—Redwood— Interior: Sheetrock—Plastered—Paneled—Cellotyx—Plywood—None.			
	Floors: Oak-Plywood-Cement-Tile-Pine-Arrock-Higgins-Terrazio-None.			
	Rooting: Shingle — Asbestos — Terra-Cotta — file — Composition — Slate — Copper — C-Iroi Tar and Grave			
	Foundation Concrete Slab — Plets — Blocks, Beams — Brick — Piers-Wood.			
	Plumbing: 1 Tile-2 Tile-3 Tile-Other: None.			
	Climatizers: Dual. Amp. Ac-Tons, Attic Ventilation-Central Heat Unit-Gas Stoves-None.			
	Electrical Equipment: Part All—Sprinklers. Condition: New—Good—Fair—Poor—Obsolete.			
	Condition: New —Good Fair —Poor — Obsolete. Permit Val 2 50 C			
	Year Built			
	129300, 270 - 41200			
	Remarks: 1993 & 31 4980			
	297° 0 100. 300			
	5080			
	Moved here From No. Sq. Ft. 2 . S. S. S. Per Sq. Ft			
	No. Sq. Ft. No. Sq. Ft. Per Sq. Ft. Per Sq. Ft.			
	1956 new Assess	ed Value of Building 2030		
	COD XEWO	A SESO	COBA	
	. (003%)			
		The state of the s		
			la .	
	3 11			
		additine :	1	
		alc-c/H-1339e.60	= 800	
	71	x Corners 10040.	- 700	
TK		Borch 240170 -	40	
90	37	Carport 2910 120	- 500	
4	Gt.	Carpon 2115	1740	
ly.	A DENT PORTER OF			
	33- 24-197.		i i	
3 24	814-	The Residence of the Control of the		
E CAR	4.16-	THE PARTY OF STREET		
77	133.9		•	
		Manager and the state of the st		
		The last which the same participation		
		The Parcy Market Street Control of the Control of t	4	

7954 Glenvista St Glenbrook Valley

CONTEXT AREA MAP




CONTEXT AREA

7947 GLENVISTA CONTRIBUTING EXAMPLE 1



7943 GLENVISTA- CONTRIBUTING EXAMPLE 2



7950 GLENVISTA (NEIGHBOR)- CONTRIBUTING EXAMPLE 3



7938 GLENVISTA- CONTRIBUTING EXAMPLE 4



SITE PHOTOS (PROVIDED BY APPLICANT AND ILMS)

EARLIER 2021 AND PRIOR FRONT



BACK/SIDE



FRONT



SIDE VIEW



12/6/2024

POST DECEMBER 2021 TO CURRENT DAY 12/2021



1/18/22



7954 Glenvista St Glenbrook Valley

3/11/22



8/11/23 - CURRENT DAY





RED TAGS THROUGHOUT 2021-2024





4/25/2022 (6th NOTICE)



4/25/2022 (6th NOTICE)



4/10/23 (15th NOTICE)




12/27/2023 (22nd NOTICE)




10/21/2023 (25th NOTICE AND MOST RECENT)



SITE PLAN




FLOOR PLAN



7954 Glenvista St Glenbrook Valley

ROOF PLAN





ELEVATIONSPREVIOUS EAST (FRONT)



CURRENT EAST



12/6/2024

PREVIOUS WEST (REAR)



CURRENT WEST



PREVIOUS SOUTH (SIDE)



CURRENT SOUTH



12/6/2024

PREVIOUS NORTH (SIDE)



CURRENT NORTH



WINDOW SCHEDULE

Window Schedule:

- 1 3'-0" Width x 5'-0" Length Single Hung Window SHGC:0.252 U-Factor:0.550
- ** All Viny

 (2) 2'-0" Width x 5'-0" Length Single Hung Window SHGC:0.252 U-Factor:0.550
 - (3) 5'-0" Width x 1'-6" Length Silding Window SHGC:0.252 U-Factor:0.550
 - (4) 3'-0" Width x 1'-6" Length Silding Window SHGC:0.252 U-Factor:0.550
 - (5) 4'-0" Width x 5'-0" Length Fixed Window SHGC:0.252 U-Factor:0.550



Houston Archaeological & Historical Commission

December 12, 2024 HPO File No. 2024_0303 7954 Glenvista St Glenbrook Valley

STATEMENT FROM 2nd INVESTIGATOR

From: Villarreal, Marco - HPW <

Sent: Tuesday, December 3, 2024 3:30 PM

To: Valley, Taylor - PD <

Subject: RE: 7954 Glenvista

Good Afternoon,

Im no longer in this division, im currently with inviormental enforcement, but I can provide you some information on this property, the previous Senior Inspector is no longer with this divion also, any questions may be answered by the acting senior Defi Smith, but I can provide some back ground on this property, previous contractor was working without a Building permit and was reported to Habability Div. Original complaint was on 12/28/2021. First attempt for a building permit was on 01/09/2022. PN 22002241. Witch was rejected. 6 citations have been issued. I have no knowledge to whom they were written to. First citation was written on 01/18/2022 and the last citation was written on 07/26/2023. A second attempt for a permit was PN 23042692, Last activity on this permit was 08/23/2024. This property requires a residential remodel permit with garage conversion, home was gutted and floor plan was changed from original floor plan, this is as much information. I can provide for this property, please address further questions to acting Senior Inspector Defi Smith, and current.

