1714 South Boulevard Boulevard Oaks

CERTIFICATE OF APPROPRIATENESS

Applicant: Adrienne E. Stokes, owner and Roger Cooner, agent

Property: 1714 South Boulevard, Tract 7A & 8A, Block 4, West Edgemont Subdivision. The property includes a historic 5,255

square foot two-story wood frame single-family residence and a detached garage situated on a 17,745 square foot (105'

x 169') interior lot.

Significance: Contributing Colonial Revival residence, constructed circa 1929, located in the Boulevard Oaks Historic District.

Proposal: Alteration – Front entry, shutters, side and rear addition

- Removal of non-original front entry with cast and wrought iron detailing with low slope metal awning that causes
 drainage issues. Sanborn maps as well as county documents from the 1930s do not show a front entry porch on the
 original structure Construct simplified metal column entryway and sloped metal roof.
- Existing historic windows that will remain will be restored. 1 historic window on the second-floor east elevation will be moved to the new addition second floor on same side. Other 2nd floor window closer to the street will remain in place within interior construction.
- Replace historic roof shingles in kind with composite shingle (exempt)
- Historic/early first and second floor to remaining is 2,390 sq ft (not including side porch). The enclosed one-story sunporch of 696 sq ft.is proposed to be demolished along with rear two-story addition of 1,943 sq ft. constructed c. 1950. The porch was enclosed also during the 1950s.
- Two story side addition will have a footprint of 377 sq ft. vs existing of 196 sq ft. New side addition is setback 3'10" from front corner; existing is 3'11". Total two-story side addition= 801 sq ft.
- Two story rear addition (including garage) will have a footprint of 2,474 sq ft. New rear addition is set-in further on both sides than existing addition. Total two-story rear addition = 4,367sqft.
- Current primary residence is 4,822 sq feet with 1,300 sq ft detached garage. Total proposed square footage including attached garage is 8,032sq ft. (essentially adding 3,210 sq ft)
- Demolish existing two-story detached garage of 1,300 sq ft located in the back of the property. A new attached garage of 732 sq ft will be constructed in a very similar position at the rear of the property
- Existing sunroom on the east side of historic home was built c.1950 which closed in the original porch with permastone and aluminum windows. Proposed 1 1/2 story addition is set back from historic front corner with lower ridge and eave heights compared to the historic portion. Partial dormers/raised eaves for second floor windows allow for addition space without raising overall height. The chimney will remain in place and new addition will be built around it. Roof will be in composite shingle. This east side addition will be clad in artisan smooth cementitious siding with mahogany paired pilasters or columns with brick plinth (painted to match historic). French doors, transoms, and windows will be metal/aluminum clad wood. See drawings and window worksheet for lite patterns and more details. Overall, windows on new addition are proposed as 6/6 lite pattern.
- Existing rear addition was also built c. 1950 where early rear kitchen once existed. This rear portion will be removed for 2 story addition and attached garage projecting back towards property line. Addition is set back from rear corners. Ridge height is lower than historic; eave is matching. Roof in composite shingle and standing seam metal (used for awnings as well). Attached garage and addition living space on second floor are in brick that match existing historic portion. Mahogany trim to match existing soffit design on all additions.
- Historic pitch is 12:12, side addition matches, and rear addition is lower at 10:12.

Public Comment: No public comment received.

Civic Association: Architectural Committee for Edgemont Civic Association is in support.

Recommendation: Approval with conditions: applicants update window lite pattern to 1/1, reduce lite pattern on

French door openings with single lite transoms (to be reviewed by staff); eliminate decorative pilasters/columns visible from the street on the south (front) and east (side) elevations. Align top

of 2nd floor windows on east side addition with the height of historic windows.

HAHC Action: -

1714 South Boulevard Boulevard Oaks

APPROVAL CRITERIA

ALTERATIONS, REHABILITATIONS, RESTORATIONS AND ADDITIONS

Sec. 33-241: HAHC shall issue a certificate of appropriateness for the alteration, rehabilitation, restoration or addition of an exterior feature of (i) any landmark, (ii) protected landmark, (iii) any building, structure or object that is part of an archaeological site, or (iv) contributing building in a historic district upon finding that the application satisfies the following criteria, as applicable:

S	D	NA		S - satisfies D - does not satisfy NA - not applicable
\boxtimes			(1)	The proposed activity must retain and preserve the historical character of the property;
\boxtimes			(2)	The proposed activity must contribute to the continued availability of the property for a contemporary use;
			(3)	The proposed activity must recognize the building, structure, object or site as a product of its own time and avoid alterations that seek to create an earlier or later appearance; 6/6 windows, seek to match historic lite patterns and look, but this copied design does not help differentiate the addition from the historic and do not appear as a product of its own time. Transoms, French doors, and columns/pilasters seek to create an earlier appearance. If applicant agrees to update windows to 1/1, they will be more distinct from historic windows and clearly appear as a product of their own time, as will the addition. If simplified, transom and French doors could be appropriate. Columns should be removed to simplify the façade as not to detract from the historic portion of the home.
			(4)	The proposed activity must preserve the distinguishing qualities or character of the building, structure, object or site and its environment; Existing front entry is not original based on Sanborn maps and Harris County Archive photos which either show no entry porch at all or a very simplified version.
\boxtimes			(5)	The proposed activity must maintain or replicate distinctive stylistic exterior features or examples of skilled craftsmanship that characterize the building, structure, object or site;
			(6)	New materials to be used for any exterior feature excluding what is visible from public alleys must be visually compatible with, but not necessarily the same as, the materials being replaced in form, design, texture, dimension and scale;
			(7)	The proposed replacement of exterior features, if any, should be based on an accurate duplication of features, substantiated by available historical, physical or pictorial evidence, where that evidence is available, rather than on conjectural designs or the availability of different architectural elements from other structures;
\boxtimes			(8)	Proposed additions or alterations must be done in a manner that, if removed in the future, would leave unimpaired the essential form and integrity of the building, structure, object or site;
			(9)	The proposed design for any exterior alterations or addition must not destroy significant historical, architectural, archaeological or cultural material, including but not limited to siding, windows, doors and porch elements and must be compatible with the size, scale, material and character of the property and the area in which it is located;
			(10)	The proposed alteration or addition must be compatible with the massing, size, scale material and character of the property and the context area; and While the rear addition is large, it is set back towards the center of the lot and is not largely visible from the street (see renderings), see contributing context and scale of additions at the end of the report for both the rear and side additions. The applicant broke up the massing for the attached garage area.
			(11)	The distance from the property line to the front and side walls, porches, and exterior features of any proposed addition or alteration must be compatible with the distance to the property line of similar elements of existing contributing structures in the context area.

July 28, 2022 HPO File No. HP2022_87 1714 South Boulevard Boulevard Oaks



PROPERTY LOCATION

BOULEVARD OAKS HISTORIC DISTRICT



Building Classification

Contributing

Non-Contributing

Park

INVENTORY PHOTO



CURRENT








Archives c. 1950






1714 South Boulevard Boulevard Oaks

ARCHIVES C. 1930 - 2, 840 SQ FT

	IMPROVEMENTS				
Map No. Addition Wedgennet	No. Price Per Sq. Ft.				
	Sq. 2840 4.50 \$ 12780				
Block - 4 Lot & 45/7 - W608	Percent/ Good				
9 1 1 -11					
OWNER Ander John	80				
ADDRESS 1714 South Blood	10220				
TYPE OF PROPERTY OCCUPIED VACANT	Other Bldgs.				
BASEMENT, Whole Part FLOORING, Pine, Hardwood, Cement, Tile, Marble, Dirt	Dav + 300				
FOUNDATION, Concrete, Stone Brick Piers Posts	2 3				
WALLS, Brick Stone INTERIOR TRIM, Plaster, Hardwood, Marble, Metal,	Total				
Hollow Tile, Stucco, Metal, Position Postures	All 10520				
Concrete Blocks, Box Weatherboard HEATING, Furnace, Stoves,	Diags.				
ROOF CONS., Concrete, Fireplace, Chimneys, Gas					
Steel, Wood Truss					
ROOF, Hip, Gable, Mansard, LIGHTING, Electricity					
Flat PLUMBING, Sewer, Water,	LAND VALUE				
ROOFING, Composition, Metal, State, Wood, Shin-	Unit Front Ft.				
gles, Tile, Asbestos ELEVATORS	Front x Depth Value Factor Value \$				
EXTERIOR TRIM, Stone, CONDITION, Good, Fair,	101 41/67 31 100 41/0				
Terra Cotta, Metal, Wood, Marble, Granite					
maior, oranic					
	TOTAL				
PERMIT DATENOAMT	1130-2926				
	113 - 275 1				



HPO File No. HP2022_87


1714 South Boulevard Boulevard Oaks

ARCHIVES C. 1930

	Form 381
	BUILDING ACSESSMENT
	Houston, Texas
	Map No. Permit No.
	Vol. Page VO
	1 2 1 192.9
	Owner A South Street or Avenue
	No. Street of Avenue
	Addition // Edgement
	Block Lot St 91 8
	7 RoBath.
	6x14 Por.
l	Size of Building
	widedeepstories
	2 Cwide 2 C deep 2 Shristories
	With or without basement or sellar
	Foundation: Walls or Piers. Material: Frame, Brick, Veeneer, Stucco.
	Outside Trimmings: Plain, Ornamental.
	Inside Finish: Rough, Plain, Ornamental, Hard Wood, Pine,
	Roof: Hip, Gable, Flat.
	Roofing: Slate, Tile, Tin, Shingle, Copper, Composition, Iron, Tar and Gravel, Paper, Asbestos.
	Heating: Furnace, Steam, Gas, Stoves, Fire Place.
	Plumbing: With or Without Bath Room, Permit Value, \$ 000
	No. Sq. Ft. Per Sq. Ft.
	No. Sq. Ft. A. T. Per Sq. Ft.
	No. Sq. Ft. Per Sq. Ft.
	Jul 26/
	a graf ition
	Assessed Value of Building, \$
	Rendered in name of
	Mit a and all
	VIII I/X (A)V()/A W()

July 28, 2022 HPO File No. HP2022_87

ARCHIVES - DATE UNKNOWN




HPO File No. HP2022_87

1714 South Boulevard Boulevard Oaks

ARCHIVES - DATE UNKNOWN


no front entry columns etc




1714 South Boulevard Boulevard Oaks


ARCHIVES - DATE UNKNOWN

#SK	Loc. 17	4 South Fiv			Edgemo	And and a second	100,00					
Br. 5 8a. 33	Den Y	Es. Sq. Ft. 500	0+	Aprx. Age 44	Vac. 'O	Lk. Bx. O S	try 4					
Lot 105' x 176	.51.	LegoE, 45	of	7. W. 60' of	8, Blk	4. West	deem					
Extr. Brick	Lv. Rm.	24.×14	Deb.	Hear central	Date 1	st P/	1					
sweeorgian	Dn. Rm.	18 ×14	Y	Cent A/C Zoned	Date 2	nd P/	1					
Roof W/S	Den [35 ×16.5	Y	Tons Aprx. Q	Escrow							
Gar. Y # Car 2	Kir.	7 21 *12	Y	A/C Units	Tot. Monthly							
Util. Rm. Y	Brk. Rm.	14 × 8	Y	Fire 2 - WB Ex. Fan	1st With							
Potio 35x12 COV	Bd. Rm.	1 21 ×17	Y	D/W Y Dsp. Y	loan #	Int	<u>%</u>					
Fodto. p/b	8d. Rm.	16 ×13.5	Y	Oven Y Range Y	Туре	Mat.						
Pool no	Bd. Rm.	18 *15	Y	Wsh. C. Y Dry C Y	2nd With	Int	*					
Corner NO	8d. 2m. 1	14 x 9	У	Sdwik. Y C/G Y	Tot. Ann. To:	\$813,62						
st. Surf. payed	Bd Rn	H 12 x 9	Y	Swr. Y Stm. SwrY	Ann. Moint.	Fee						
Refin. Cash or new conventional Fenced Yes												
Sch. Elm. Poe					amar	OtherSt. Jo	ohn's					
Owner Mrs. B	arbara	Hill, feme	S	ole Ph 524	-4577	Possnnepot'	iable					
Realtor # 137, N	ary T	Clegg (Su	sie	e Herring 52	6-4011	N/Ph 781.	-1849					
Remorks: In addition to above: large entry hall, garden room.												
library, an	library, and quarters. Dressing room off master bedroom, High											
ceilings.	ceilings. Great charm and super location.											
6%	3%	Key M	ap P	1094922 Map).	Grid 3	566-3555						





ARCHIVES C. 1968 -simplified front entry



HPO File No. HP2022_87

ARCHIVES C. 1968 - simplified front entry



CURRENT PHOTO



CURRENT PHOTOS



CURRENT PHOTOS – ENCLOSED PORCH/ C. 1950S ADDITION TO BE REMOVED



CURRENT PHOTOS - REAR ADDITION- TO BE REMOVED



CURRENT PHOTOS – REAR ADDITION- TO BE REMOVED



RENDERINGS EXISTING



PROPOSED - VIEW 5



RENDERINGS

EXISTING



PROPOSED - VIEW 6



RENDERINGS EXISTING



PROPOSED - VIEW 4



RENDERINGS EXISTING



PROPOSED - VIEW 3



RENDERINGS EXISTING



PROPOSED - VIEW 2



RENDERINGS EXISTING



PROPOSED - VIEW 1




CONTEXT: 1714 AND 1710 SOUTH BLVD



INVENTORY PHOTO: 1710 SOUTH BVLD



RENDERING PLAN/POINT OF VIEW VIEWS 1-6



SOUTH - FRONT ELEVATION FACING SOUTH BLVD EXISTING



Second Design Review



CURRENT PROPOSAL



NORTH ELEVATION - REAR FACING ALLEY

EXISTING



Second Design Review



CURRENT PROPOSAL



ITEM A.12

1714 South Boulevard Boulevard Oaks

July 28, 2022 HPO File No. HP2022_87

WEST SIDE ELEVATION



Second Design Review




CURRENT PROPOSAL



1714 South Boulevard **Boulevard Oaks**

EAST SIDE ELEVATION








SITE PLAN FIRST FLOOR PLAN


EXISTING - Rear and Side addition removal






FIRST FLOOR PLAN


PROPOSED



HPO File No. HP2022_87









ROOF/SITE PLAN


EXISTING 2nd Design Review



ROOF/SITE PLAN



ROOF/SITE PLAN



July 28, 2022 HPO File No. HP2022_87

CERTIFICATE OF APPROPRIATENESS



WINDOW WORKSHEET

	EXISTING WINDOW SCHEDULE											
Window	w Material Lite Style Dimensions Recessed/Inset C					Original/	Existing to					
		Pattern				Replacement	Remain					
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Original	No					
E1	Wood	6/6	DH	34 x 55	Recessed	Original	Yes					
E2	Wood	6/6	DH	34 x 55	Recessed	Original	Yes					
E3	Wood	6/6	DH	34 x 55	Recessed	Original	Yes					
E4	Wood	6/6/6	TH	34 x 80	Recessed	Original	Yes					
E5	Wood	6/6/6	TH	34 x 80	Recessed	Original	Yes					
E6	Wood	3/1	Fixed	16 x 50	Recessed	Original	Yes					
E7	Wood	3/1	Fixed	16 x 50	Recessed	Original	Yes					
E8	Wood	6/6	DH	34 x 68	Recessed	Original	Yes					
E9	Wood	6/6/6	TH	34 x 80	Recessed	Original	Yes					

	DAMAGE TO EXISTING WINDOWS								
Window	Describe Damage								
Ex. A1	Glass is broke, window is inoperable, rail is rotten, and frame is broken								

	PROPOSED WINDOW SCHEDULE										
Window	Material	Lite Pattern	Style	Dimensions	Recessed/ Inset	Brand/ Vendor	Other				
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Plygem					
101	Wood	2/12	Fixed	24 x 80	Recessed	Custom	Match exist.				
102	Wood	6/6/6	TH	34 x 80	Recessed	Custom	Match exist.				
103	Wood	2/12	Fixed	24 x 80	Recessed	Custom	Match exist.				
104	Mtl. Clad	6/6/6	TH	34 x 80	Recessed	Marvin					
105	Mtl. Clad	6/6/6	TH	34 x 80	Recessed	Marvin					
106	Mtl. Clad	2/4	DH	24 x 63	Recessed	Marvin	With transom				
107	Mtl. Clad	4/8	DH	46 x 63	Recessed	Marvin	With transom				
108	Mtl. Clad	4/8	DH	46 x 63	Recessed	Marvin	With transom				
109	Mtl. Clad	2/4	DH	24 x 63	Recessed	Marvin	With transom				

- Must include photos of all windows with labels indicated on this sheet
- Must include manufacture's specifications and details for all proposed windows

CERTIFICATE OF APPROPRIATENESS



WINDOW WORKSHEET

	EXISTING WINDOW SCHEDULE										
Window	Vindow Material Lite Style Dimensions Recessed/Inset Original/ Pattern Pattern										
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Original	No				
E10	Wood	6/6/6	TH	34 x 80	Recessed	Original	Yes				
E11	Wood	6/6	DH	34 x 55	Recessed	Original	Yes				
E12	Wood	6/6	DH	34 x 55	Recessed	Original	Yes				
E13	Wood	8/8	DH	45 x 67	Recessed	Original	Yes				
E14	Wood	4/4	DH	24 x 67	Recessed	Original	Yes				
E14A	Wood	6/6	DH	27 x 46	Recessed	Original	Yes				
E15	Wood	6/6	DH	34 x 67	Recessed	Original	Yes				
E16	Wood	4/4	DH	24x 67	Recessed	Original	Yes				
E16A	Wood	6/6	DH	27 x 46	Recessed	Original	Yes				

	DAMAGE TO EXISTING WINDOWS								
Window	Describe Damage								
Ex. A1	Glass is broke, window is inoperable, rail is rotten, and frame is broken								

	PROPOSED WINDOW SCHEDULE										
Window	Material	Lite	Style	Dimensions	Recessed/	Brand/	Other				
		Pattern			Inset	Vendor					
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Plygem					
110	Mtl. Clad	6/6/6	TH	34 x 80	Recessed	Marvin					
111	Mtl. Clad	2/3	Fixed	24 x 44	Recessed	Marvin					
112	Mtl. Clad	3/3	Fixed	32 x 44	Recessed	Marvin					
113	Mtl. Clad	2/3	Fixed	24 x 44	Recessed	Marvin					
114	Mtl. Clad	2/3	Fixed	24 x 44	Recessed	Marvin					
115	Mtl. Clad	2/3	Fixed	24 x 44	Recessed	Marvin					
116	Mtl. Clad	1/4	DH	12 x 57	Recessed	Marvin	With transom				
117	Mtl. Clad	8/8	DH	42 x 57	Recessed	Marvin	With transom				
118	Mtl. Clad	1/4	DH	12 x 57	Recessed	Marvin	With transom				

Must include nhotos of all windows with labels indicated on this sheet

	EXISTING WINDOW SCHEDULE											
Window	ndow Material Lite Style Dimensions Recessed/Inset Original/ Pattern Replacement											
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Original	No					
E17	Wood	8/8	DH	45 x 67	Recessed	Original	Yes					
E18	Wood	6/6	DH	34 x 58	Recessed	Original	Yes, Relocate					

	DAMAGE TO EXISTING WINDOWS								
Window	Describe Damage								
Ex. A1	Glass is broke, window is inoperable, rail is rotten, and frame is broken								

	PROPOSED WINDOW SCHEDULE										
Window	Material	Lite	Style	Dimensions	Recessed/	Brand/	Other				
		Pattern			Inset	Vendor					
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Plygem					
119	Mtl. Clad	1/4	DH	12 x 57	Recessed	Marvin	With transom				
120	Mtl. Clad	8/8	DH	42 x 57	Recessed	Marvin	With transom				
121	Mtl. Clad	1/4	DH	12 x 57	Recessed	Marvin	With transom				
122	Mtl. Clad	6/6	DH	34 x 55	Recessed	Marvin					
201	Mtl. Clad	2/3	Fixed	24 x 44	Recessed	Marvin					
202	Mtl. Clad	6/6	DH	34 x 58	Recessed	Marvin					
203	Mtl. Clad	6/6	DH	34 x 58	Recessed	Marvin					
204	Mtl. Clad	6/6	DH	34 x 58	Recessed	Marvin					
205	Mtl. Clad	6/6	DH	34 x 58	Recessed	Marvin					

Bitual hadroda abasas of all reladance relabilitation ladicated as the chast

	PROPOSED WINDOW SCHEDULE										
Window	Material	Lite Pattern	Style	Dimensions	Recessed/ Inset	Brand/ Vendor	Other				
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Plygem					
206	Mtl. Clad	6/6	DH	34 x 58	Recessed	Marvin					
207	Mtl. Clad	6/6	DH	34 x 58	Recessed	Marvin					
208	Mtl. Clad	2/3	Fixed	24 x 44	Recessed	Marvin					
209	Mtl. Clad	6/6	DH	34 x 58	Recessed	Marvin					
210	Mtl. Clad	6/6	DH	34 x 58	Recessed	Marvin					
211	Mtl. Clad	12/12	DH	72 x 58	Recessed	Marvin					
212	Mtl. Clad	12/12	DH	72 x 58	Recessed	Marvin					
213	Mtl. Clad	12/12	DH	72 x 58	Recessed	Marvin					
214	Mtl. Clad	8/8	DH	54 x 58	Recessed	Marvin					

	PROPOSED WINDOW SCHEDULE										
Window	Material	Lite Pattern	Style	Dimensions	Recessed/ Inset	Brand/ Vendor	Other				
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Plygem					
215	Mtl. Clad	8/8	DH	54 x 58	Recessed	Marvin					
216	Mtl. Clad	6/6	DH	34 x 58	Recessed	Marvin					
217	Mtl. Clad	6/6	DH	34 x 58	Recessed	Marvin					
218	Mtl. Clad	6/6	DH	34 x 58	Recessed	Marvin					
219	Mtl. Clad	6/6	DH	34 x 58	Recessed	Marvin					
220	Mtl. Clad	6/6	DH	34 x 58	Recessed	Marvin					
221	Mtl. Clad	2/3	Fixed	24 x 44	Recessed	Marvin					
222	Mtl. Clad	4/4	DH	24 x 58	Recessed	Marvin					
223	Mtl. Clad	6/6	DH	34 x 58	Recessed	Marvin					

	PROPOSED WINDOW SCHEDULE										
Window	Material	Lite Pattern	Style	Dimensions	Recessed/ Inset	Brand/ Vendor	Other				
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Plygem					
224	Mtl. Clad	4/4	DH	24 x 58	Recessed	Marvin					
225	Mtl. Clad	4/4	DH	24 x 58	Recessed	Marvin					
226	Mtl. Clad	6/6	DH	34 x 58	Recessed	Marvin					
227	Mtl. Clad	4/4	DH	24 x 58	Recessed	Marvin					
228	Mtl. Clad	6/6	DH	34 x 58	Recessed	Marvin					
229	Mtl. Clad	6/6	DH	34 x 58	Recessed	Marvin					
230	Mtl. Clad	2/3	Fixed	24 x 44	Recessed	Marvin					
231	Mtl. Clad	12/12	DH	72 x 58	Recessed	Marvin					
232	Mtl. Clad	12/12	DH	72 x 58	Recessed	Marvin					

Must include photos of all windows with labels indicated on this sheet

July 28, 2022 HPO File No. HP2022_87

•	•							
		_				$\overline{}$		
		ВС	oule	eva	rd	O a	aks	,

PROPOSED WINDOW SCHEDULE								
Window	Material	Lite	Style	Dimensions	Recessed/	Brand/	Other	
		Pattern			Inset	Vendor		
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Plygem		
233	Mtl. Clad	6/6	DH	34 x 58	Recessed	Marvin		
234	Mtl. Clad	2/3	Fixed	24 x 44	Recessed	Marvin		



Window characteristics-

- · Metal clad exterior frame and muntins with pre-finished factory color (white to match existing)
- Wood interior frame and muntins (to be painted)
- · Insulated glass
- Stainless steel spacer bar at frame and muntins simulates the appearance of true divided lights while allowing window to meet energy conservation requirements
- Muntins are available in 5/8" width which will match existing muntin width (historic windows tend to have narrow width muntins)
- · Light divisions and sizes are available that will closely mirror the dimensions of the existing windows

APPLICANT ATTACHMENTS: EMAIL FROM STEPHEN FOX/SANBORN

From: Stephen Fox <<u>sfox@rice.edu</u>> Date: Thu, Aug 12, 2021 at 4:06 PM Subject: Re: 1714 South Blvd

To: Adrienne Stokes <4astokes@gmail.com>

Adrienne.

Thank you for giving me a tour of your house.

I'm impressed with the research you've been able to compile on the house.

I remembered one other source: the Sanborn Company's Insurance Maps of Houston TX of 1925, as revised through February 1950, which I have online access to through Rice University's Fondren Library.

I attach the outline of your house below. What took me by surprise is that no front porch is shown at all.

It never occurred to me that the front porch could be a later addition.

The diagram does show a one-story porch projecting from the east side of the living room (most likely a screened porch), and a one-story northwest rear projection (the original kitchen) and a small back porch.

Usually, the Sanborn diagrams are quite accurate.

Thank you also for the exceptionally generous gift certificate to the Raven, a traditional hangout of mine.

Here is a link to the catalogue of the Weber-Staub-Briscoe Architectural Collection at the Woodson Research Center (the archives division) of the Fondren Library at Rice University. <a href="https://onesearch.library.rice.edu/discovery/fulldisplay?docid=alma991012792779705251&context=L&vid=01RICE_INST:RICE&lang=en&search_scope=MyInst_and_CI&adaptor=Loca_1%20Search%20Engine&tab=Everything&query=any.contains,staub%20Briscoe&mode=basica&offset=0

Dara Flinn <dflinn@rice.edu> is the archivist who processed the collection.

Best SF

LINK:

Here is a link to the catalogue of the Weber-Staub-Briscoe Architectural Collection at the Woodson Research Center (the archives division) of the Fondren Library at Rice University.

https://onesearch.library.rice.edu/discovery/fulldisplay?docid=alma991012792779705251&context=L&vid=01RICE_INST: RICE&lang=en&search_scope=MyInst_and_CI&adaptor=Local%20Search%20Engine&tab=Everything&query=any,contains,staub%20Briscoe&mode=basic&offset=0

HPO File No. HP2022_87

Detail References from Homeowner FOR FRONT ENTRY METAL WORK/COLUMNS

Sam Dixon Design Example: 1216 Bissonet







Certificate Of Appropriateness:

Contributing Context Worksheet New Construction and Addition



Address: 1714 South Blvd, Houston, TX, 77098

Primary Building or Accessory Structure

For New Construction:

Based on Sec. 33-242 of the Historic Preservation ordinance, new construction in a historic district must be **compatible** with exterior features of contributing structures in the context area (same historic district). When designing, elements of existing contributing construction in this district should be referenced, but not necessarily copied. Please give at least three examples of contributing buildings referenced. See this link for new construction criteria:

https://bit.ly/3xG3NqJ

Neighboring Contributing Context Address (Reference Adress in same historic district)	Number of stories	Ridge Height *If available	Compatibility/Reference Reason Examples: massing, cladding, etc.
1740 South Blvd, Houston, TX, 77098	2		Massing, secondary front structure
1707 South Blvd, Houston, TX, 77098	2		Massing, secondary front structure
1603 North Blvd, Houston, TX, 77098	2		Massing, secondary front structure
Neighboring Context Address * if next door neighbor isn't contributing	Number of stories	Ridge Height *if available	

For an Addition:

Based on Sec. 33-241 for Alterations, Rehabilitations, Restorations and Additions:

- The proposed alteration or addition must be compatible with the massing, size, scale material and character of the
 property and the context area; and
- The distance from the property line to the front and side walls, porches, and exterior features of any proposed addition or alteration must be compatible with the distance to the property line of similar elements of existing contributing structures in the context area.

Existing contributing structures must be in the context area (same historic district). Elements of existing contributing construction in this district should be referenced in the design process. Please give at least three examples of these contributing buildings. See this link for alteration criteria:

https://bit.ly/3wEYfMa

Neighboring Contributing Context Address (Reference Adress in same historic district)	Number of stories	Ridge Height *If available	Compatibility/Reference Reason examples: massing, cladding, etc.
1932 South Blvd, Houston, TX, 77098	2		Rear addition with varying roof heights
1659 South Blvd, Houston, TX, 77098	2		Rear addition with varying roof heights
1702 South Blvd, Houston, TX, 77098	2		Rear addition with varying roof heights
Neighboring Context Address * if next door neighbor isn't contributing	Number of stories	Ridge Height *if available	

APPLICANT PHOTOS -CONTEXT, 1707 SOUTH BLVD_PRECEDENT 1, CONTRIBUTING COLONIAL REVIVAL C. 1927

SETBACK SIDE ADDITION, RAISED ROOFLINE
CURRENT LIVING AREA 5,794SQFT AND 26,684 SQFT LOT

SIDE ADDITION EXISTED BEFORE DISTRICT CREATED



INVENTORY PHOTO:



HPO File No. HP2022_87


APPLICANT PHOTOS -CONTEXT, 1710 SOUTH BLVD_PRECEDENT 2, CONTRIBUTING COLONIAL REVIVAL C. 1928,

SETBACK SIDE ADDITION REFERENCE, REMODELED C. 2010 AND C. 2011, CURRENT LIVING AREA 4,262 SQ FT ON 15,210 SQFT LOT

SIDE ADDITION EXISTED BEFORE DISTRICT CREATED



INVENTORY PHOTO:



APPLICANT PHOTOS -CONTEXT, 1740 SOUTH BLVD_PRECEDENT 3 CONTRIBUTING MANORIAL C. 1936

SETBACK SIDE ADDITION, RAISED ROOFLINE
CURRENT LIVING AREA 5,794SQFT AND 26,684 SQFT LOT
SIDE ADDITION EXISTED BEFORE DISTRICT CREATED

CURRENT:



INVENTORY PHOTO:



ADDITIONAL CONTEXT: 1702 SOUTH BLVD, REMODELED 2018, APPROVED BY HAHC 2/23/2017

c.1927, Contributing Colonial Revival, **7,509 sq ft living area on 13,267 sq ft lot**, (56%) CURRENT CORNER VIEW:

- Remove an existing 1,085 square foot 1980s one -story addition on the rear (north) elevation of the two-story residence.
- Construct a rear 2,836 square foot one and two-story addition with a detached garage.







INVENTORY PHOTO:


CURRENT AERIAL:





ADDITIONAL CONTEXT: 1932 SOUTH BLVD/5115 HAZARD ST, REMODELED 2017, Partially Approved by HAHC 10/18/2018

c.1936, Contributing Colonial Revival, 6.215 sq ft living area on 8,095 sq ft lot, (%) CURRENT CORNER VIEW:





CURRENT:



INVENTORY:



ADDITIONAL CONTEXT: 1659 SOUTH BLVD, REMODELED 2009, before district was created

c.1928, Contributing Tudor Revival, 7,684 sq ft living area on 22,176 sq ft lot (34%), CURRENT CORNER VIEW:





ADDITIONAL CONTEXT: 1659 SOUTH BLVD,

REMODELED 2009, before district was created

c.1928, Contributing Tudor Revival, 7,684 sq ft living area on 22,176 sq ft lot, CURRENT CORNER VIEW:





c. 2007 BEFORE ADDITION:



INVENTORY PHOTO:



CONTRIBUTING CONTEXT: 1660 South Blvd (corner lot)

Lot size: 24,505 sqft – Living Space 6,137 sq ft (25%)

Addition approved by HAHC c. 2013







APPLICANT'S ADDITIONAL PROPOSALS BASED ON CONDITIONS

1/1 windows on addition with **smooth cementitious siding**, two versions of trim detail – to be described by applicant



APPLICANT'S ADDITIONAL PROPOSALS BASED ON CONDITIONS

1/1 windows on **brick** addition - to be described by applicant



Edgemont Approval:

From: Adrienne Stokes

 To:
 Coleman, Amanda - PD; Roger Cooner

 Subject:
 Fwd: 1714 South Blvd Proposed Plans

 Date:
 Wednesday, July 27, 2022 4:24:49 PM

 Attachments:
 A-001 Proposed Site Plan.pdf

A-101 Proposed Site Plan.pdf A-101 Proposed First Floor Plan.pdf

A-201 Existing and Proposed South Elevation.pdf A-202 Existing and Proposed North Elevation.pdf A-203 Existing and Proposed East Elevation.pdf A-204 Existing and Proposed West Elevation.pdf

AE-001 Existing Site Plan.pdf

[Message Came from Outside the City of Houston Mail System]

Sent from my iPad

Begin forwarded message:

From: Rick Jenner <rjenner@endeavorgas.com>

Date: July 27, 2022 at 4:11:03 PM CDT
To: Adrienne Stokes <4astokes@gmail.com>
Subject: FW: 1714 South Blvd Proposed Plans

Adrienne-

As discussed, the Architectural Committee for Edgemont Civic Association has voted to recommend approval for your planned remodel (submitted in your email dated July 1 and attached hereto) to the Edgemont Civic Association board. We understand that you have been in discussions with the HAHC, and they may require further modifications in order to meet their requirements. Please advise us as to whether any changes will be made to the attached set of plans, so that a proper set can be forwarded to the Edgemont board.

Best of luck with the planned construction. It looks as though it will be an excellent addition to the neighborhood.

Rick Jenner

Chair, Edgemont Architectural Committee