## CERTIFICATE OF APPROPRIATENESS

Application Date: Oct. 31, 2023

Applicant: Joey Hernandez, agent for Franklin Jones, owner

Property: 1022 Columbia Street, Lot 18, Block 221, Houston Heights Neighborhood

Subdivision. The property includes a historic 1,341 SF, one-story wood single-family residence and 620 SF detached garage apartment situated

on a 6,600 SF (50' x 132') interior lot.

Significance: Contributing Bungalow style residence, constructed circa 1915, located in

the Houston Heights South Historic District. Had COA in September 2023 for an 875 SF one-story rear addition, with garage being exempt from

work, which has not yet been built.

**Proposal:** Alteration – Noncontributing Garage

- 311 complaint and building inspector at site, 8/17/2023
  - Unpermitted work for the following:
    - Garage conversion
    - Electrical
    - Plumbing
    - Structural
- A total of 6 red tag notices between 8/2023 to 12/2023 with multiple follow-up visits by inspector
  - Most recent inspector follow-up on 11/30
- Scope of work includes:
  - Repairs to existing siding and trim
  - o Removal of non-original windows and doors on west garage wall
  - Removal of garage door and installation of new doors on west wall
  - Addition of new garage door on east garage wall at alley access

Public Comment: No public comment received.

Civic Association: No comment received.

Recommendation: Approval

HAHC Action: -

**ITEM E6** 

December 14, 2023 HPO File No. 2023\_0267 1022 Columbia St. Houston Heights South

#### **APPROVAL CRITERIA**

#### ALTERATIONS TO NONCONTRIBUTING STRUCTURES

Sec. 33-241.1(b): Director shall issue a certificate of appropriateness for the alteration, rehabilitation, or restoration of a non-contributing structure or an addition to a **noncontributing structure in an historic district** upon finding that the application satisfies the following criteria, as applicable:

1022 Columbia St. Houston Heights South

LOT SIZE	MAXIMUM LOT COVERAGE
<4000	.44 (44%)
4000-4999	.44 (44%)
5000-5999	.42 (42%)
6000-6999	.40 (40%)
7000-7999	.38 (38%)
8000÷	.38 (38%)

Existing Lot Size: 6,600

Max. Allowed: 2,640

Proposed Lot Coverage: 2,216

Remaining Amount: 424

	Maximum Floor Area Ratio	(Addition and I	New Construction)
--	--------------------------	-----------------	-------------------

LOT SIZE	MAXIMUM FAR
<4000	.48
4000-4999	.48
5000-5999	.46
6000-6999	.44
7000-7999	.42
8000+	.40

Existing Lot Size: 6,600

Max. FAR Allowed: 2,904


Proposed FAR: 2,308

Remaining Amount: 596

#### **PROPERTY LOCATION**







## **INVENTORY PHOTO**




**CURRENT PHOTO** 



## **AERIAL VIEW OF PROPERTY**



## **SANBORN (1924-1951)**



ITEM E6


## **CONTEXT AREA**



1024 Columbia Street - Contributing



1033 Columbia Street - Contributing




1015 Columbia Street - Contributing




1006 Columbia Street - Contributing

#### **SITE PLAN**




#### **FLOOR PLAN**




1022 Columbia St. Houston Heights South

## FRONT (WEST) ELEVATION FACING COLUMBIA ST.




# LEFT (NORTH) ELEVATION FACING E. 11<sup>TH</sup> ST.

#### **EXISTING**




## RIGHT (EAST) ELEVATION FACING OXFORD ST.




# REAR (SOUTH) ELEVATION FACING E 10<sup>TH</sup> ST.

#### **EXISTING**




1022 Columbia St. Houston Heights South

## **WINDOW AND DOOR SCHEDULE**



		WINDOWS	SCHEDULE		
WINDOW	MATERIAL	HEIGHT (in)	WIDTH	TYPE	NOTES
1	WOOD	40"	32"	DOUBLE HUNG	REMOVED
2	WOOD	40"	32"	DOUBLE HUNG	REMOVED
3	WOOD	35"	31"	DOUBLE HUNG	EXISTING TO REMAIN
4	WOOD	51"	31"	DOUBLE HUNG	EXISTING TO REMAIN




	EXTE	RIOR DOOR SCHE	DULE	
DOOR NO.	SIZE (WXH)	FRAME TYPE	FIRE RATING	NOTES
×	6/0 × 6/8	WOOD	N/A	REMOVED
X	3/0 x 6/8	WOOD	N/A	REMOVED
A	DBL 3/0 X 6/8	WOOD	N/A	FULL VIEW DOORS
В	3/0 X 6/8	WOOD	N/A	FULL VIEW DOORS
C	12'X7'	ALUMINUM	N/A	GARAGE DOOR

HPO File No. 2023\_0267

ITEM E6 1022 Columbia St. Houston Heights South

# **Photos Provided by Staff**





See attachments for garage context and building inspector's photos







11/08/2023

1022 COLUMBIA ST
HOUSTON TX 77008

1. UPON OPENING UP EXTERIOR WALL ON THE EAST SIDE OF THE EXISTING GARAGE ALLEY ACCESS AREA, THE OWNER DISCOVERED THE ORIGINAL GARAGE OVERHEAD DOOR OPENING AND DECIDED TO MOVE THE GARAGE DOOR TO THAT SIDE OF THE GARAGE. THIS GARAGE IS A NON CONTRIBUTING STRUCTURE AND WAS REMODELED AT SOME POINT IN THE PAST PRIOR TO CURRENT OWNER PURCHASING THE PROPERTY.



# 1022 COLUMBIA ST. 1st NOTICE #23079141

**INVESTIGATIONS** 

**INSPECTOR 155** 

Date: 08.18.23































































