CERTIFICATE OF APPROPRIATENESS

Applicant: Miguel A. Talamantes, agent for Ryan Writt, owner

Property: 524 Euclid St, Tracts 6 & 7A, Block 23. Woodland Heights Subdivision. The property includes a

two-story wood frame 1,510 square foot single-family residence situated on a 5,000 square foot

interior lot.

Significance: Contributing Craftsman house, constructed circa 1915, located in the Woodlan Heights Historic

District.

Proposal: Alteration- Addition

The applicant is proposing to construct a two-story 974 square foot addition and attached garage to the existing structure.

Smooth cementitious siding with 5" reveal

Proposed windows to be vinyl and inset and recessed

• 4/12 hipped roof with asphalt shingles

• 27'-8" max ridge height

• 23' max eave height

• Original corners to be maintained

Public Comment: No public comment received

Civic Association:

Recommendation: Approval with the condition that windows to be reviewed by staff when vendor is chosen

HAHC Action:

ITEM A.4

February 15, 2024 HPO File No. 2023_0271 524 Euclid St Woodland Heights

ALTERATIONS, REHABILITATIONS, RESTORATIONS AND ADDITIONS

Sec. 33-241: HAHC shall issue a certificate of appropriateness for the alteration, rehabilitation, restoration or addition of an exterior feature of (i) any landmark, (ii) protected landmark, (iii) any building, structure or object that is part of an archaeological site, or (iv) contributing building in a historic district upon finding that the application satisfies the following criteria, as applicable:


S	D	NA		S - satisfies D - does not satisfy NA - not applicable
\boxtimes			(1)	The proposed activity must retain and preserve the historical character of the property;
			(2)	The proposed activity must contribute to the continued availability of the property for a contemporary use;
			(3)	The proposed activity must recognize the building, structure, object or site as a product of its own time and avoid alterations that seek to create an earlier or later appearance;
			(4)	The proposed activity must preserve the distinguishing qualities or character of the building, structure, object or site and its environment;
			(5)	The proposed activity must maintain or replicate distinctive stylistic exterior features or examples of skilled craftsmanship that characterize the building, structure, object or site;
			(6)	New materials to be used for any exterior feature excluding what is visible from public alleys must be visually compatible with, but not necessarily the same as, the materials being replaced in form, design, texture, dimension and scale;
\boxtimes			(7)	The proposed replacement of exterior features, if any, should be based on an accurate duplication of features, substantiated by available historical, physical or pictorial evidence, where that evidence is available, rather than on conjectural designs or the availability of different architectural elements from other structures;
			(8)	Proposed additions or alterations must be done in a manner that, if removed in the future, would leave unimpaired the essential form and integrity of the building, structure, object or site;
			(9)	The proposed design for any exterior alterations or addition must not destroy significant historical, architectural, archaeological or cultural material, including but not limited to siding, windows, doors and porch elements;
			(10)	The proposed alteration or addition must be compatible with the massing, size, scale material and character of the property and the context area; and
			(11)	The distance from the property line to the front and side walls, porches, and exterior features of any proposed addition or alteration must be compatible with the distance to the property line of similar elements of existing contributing structures in the context area

524 Euclid St Woodland Heights




PROPERTY LOCATION

WOODLAND HEIGHTS HISTORIC DISTRICT



Building Classification



INVENTORY PHOTO




CURRENT PHOTO



AERIAL VIEW OF PROPERTY




SANBORN (1924-1950)



524 Euclid St Woodland Heights

HARRIS COUNTY BUILDING ASSESSMENT (1965)






CONTEXT AREA


520 EUCLID-CONTRIBUTING (NEIGHBOR)




514 EUCLID-CONTRIBUTING



521 EUCLID-CONTRIBUTING



510 EUCLID-CONTRIBUTING



SITE PHOTOS PROVIDED BY APPLICANT

FRONT/NORTH



REAR/SOUTH




WEST



EAST





SITE PLANS




FLOOR PLANS


EXISTING





PROPOSED







1 PROPOSE 1st FLOOR PLAN

2 PROPOSE 2nd FLOOR PLAN

ROOF PLANS








2 PROPOSE ROOF PLAN


2/12/2024


ELEVATIONS** (TO BE SHADED FOR CLARITY)


EXISTING NORTH (FRONT)



EXISTING SOUTH (REAR)







524 Euclid St Woodland Heights

WINDOW SCHEDULE**

CERTIFICATE OF APPROPRIATENESS



WINDOW WORKSHEET

EXISTING WINDOW SCHEDULE									
Window	Material	Lite	Style	Dimensions	Recessed/Inset	Original/	Existing to		
		Pattern				Replacement	Remain		
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Original	No		
1 (FRONT COUNTERCLO	WOOD	4X4 / 1/1	SH	32x72	INSET & RECESSED	ORIGINAL	YES		
2	WOOD	2X7	FIX	16x54	INSET & RECESSED	ORIGINAL	YES		
3	WOOD	3X4 / 1/1	SH	24x72	INSET & RECESSED	ORIGINAL	YES		
4	WOOD	4X4 / 1/1	SH	36x72	INSET & RECESSED	ORIGINAL	YES		
5	WOOD	3X4 / 1/1	SH	24x72	INSET & RECESSED	ORIGINAL	YES		
6	WOOD	4X4 / 1/1	SH	32x72	INSET & RECESSED	ORIGINAL	YES		
7	WOOD	4X4 / 1/1	SH	32x72	INSET & RECESSED	ORIGINAL	YES		
8	WOOD	1X1 / 1X1	SH	32x48	INSET & RECESSED	ORIGINAL	YES		
9	WOOD	1X1 / 1X1	SH	32x48	INSET & RECESSED	ORIGINAL	YES		

	DAMAGE TO EXISTING WINDOWS									
Window	/indow Describe Damage									
Ex. A1	Glass is broke, window is inoperable, rail is rotten, and frame is broken									

PROPOSED WINDOW SCHEDULE										
Window	Material	Lite	Style	Dimensions	Recessed/	Brand/	Other			
		Pattern			Inset	Vendor				
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Plygem				
26	VINYL	1X1 / 1X1	SH	32X48	INSET & RECESSED	TBD				
27	VINYL	1X1 / 1X1	SH	32X48	INSET & RECESSED	TBD				
28	VINYL	1X1 / 1X1	SH	32X48	INSET & RECESSED	TBD				
29	VINYL	1X1 / 1X1	SH	36X60	INSET & RECESSED	TBD				
30	VINYL	1X1 / 1X1	SH	36X60	INSET & RECESSED	TBD				
31	VINYL	1X1 / 1X1	SH	36X60	INSET & RECESSED	TBD				
32	VINYL	1X1 / 1X1	SH	36X60	INSET & RECESSED	TBD				
33	VINYL	1X1 / 1X1	SH	36X60	INSET & RECESSED	TBD				
34	VINYL	1X1	FIXED	36X16	INSET & RECESSED	TBD				

CERTIFICATE OF APPROPRIATENESS



WINDOW	WORKSHEET
--------	-----------

EXISTING WINDOW SCHEDULE									
Window	Window Material Lite Style D				Recessed/Inset	Original/	Existing to		
		Pattern				Replacement	Remain		
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Original	No		
10	WOOD	1X1 / 1X1	SH	32x48	INSET & RECESSED	ORIGINAL	YES		
11	WOOD	1X1 / 1X1	SH	32x72	INSET & RECESSED	ORIGINAL	NO		
12	WOOD	1X1 / 1X1	SH	32x72	INSET & RECESSED	ORIGINAL	NO		
13	WOOD	1X1 / 1X1	SH	32x72	INSET & RECESSED	ORIGINAL	NO		
14	WOOD	1X1 / 1X1	SH	32x72	INSET & RECESSED	ORIGINAL	YES		
15	WOOD	1X1 / 1X1	SH	32x72	INSET & RECESSED	ORIGINAL	YES		
16	WOOD	1X1 / 1X1	SH	32x48	INSET & RECESSED	ORIGINAL	NO		
17	WOOD	1X1 / 1X1	SH	32x72	INSET & RECESSED	ORIGINAL	YES		
18	WOOD	1X1 / 1X1	SH	32x72	INSET & RECESSED	ORIGINAL	YES		

	DAMAGE TO EXISTING WINDOWS								
Window	Nindow Describe Damage								
Ex. A1	Glass is broke, window is inoperable, rail is rotten, and frame is broken								

PROPOSED WINDOW SCHEDULE										
Window	/indow Material Lite		Style	Dimensions	Recessed/	Brand/	Other			
		Pattern			Inset	Vendor				
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Plygem				
35	1X1	1X1 / 1X1	FIXED	36X16	INSET & RECESSED	TBD				
36	VINYL	1X1 / 1X1	SH	36X60	INSET & RECESSED	TBD				
37	VINYL	1X1 / 1X1	SH	36X60	INSET & RECESSED	TBD				
38	VINYL	1X1 / 1X1	SH	36X60	INSET & RECESSED	TBD				
39	VINYL	1X1 / 1X1	SH	36X60	INSET & RECESSED	TBD				
40	VINYL	1X1 / 1X1	SH	36X16	INSET & RECESSED	TBD				
41	VINYL	1X1	FIXED	48X36	INSET & RECESSED	TBD				
42	VINYL	1X1 / 1X1	SH	36X60	INSET & RECESSED	TBD				
43	VINYL	1X1 / 1X1	SH	36X60	INSET & RECESSED	TBD				



EXISTING WINDOW SCHEDULE									
Window	Window Material Lite			Style Dimensions Recessed/Inset		Original/	Existing to		
		Pattern				Replacement	Remain		
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Original	No		
19	WOOD	1X1 / 1X1	SH	32x72	INSET & RECESSED	ORIGINAL	YES		
20	WOOD	4X4	FIX	36x36	INSET & RECESSED	ORIGINAL	YES		
21	WOOD	4X4	FIX	36x36	INSET & RECESSED	ORIGINAL	YES		
22	WOOD	4X4	FIX	36x36	INSET & RECESSED	ORIGINAL	YES		
23	WOOD	4X4	FIX	36x36	INSET & RECESSED	ORIGINAL	YES		
24	WOOD	4X4	FIX	36x36	INSET & RECESSED	ORIGINAL	YES		
25	WOOD	4X4	FIX	36x36	INSET & RECESSED	ORIGINAL	YES		

	DAMAGE TO EXISTING WINDOWS							
Window Describe Damage								
Ex. A1	Glass is broke, window is inoperable, rail is rotten, and frame is broken							

PROPOSED WINDOW SCHEDULE										
Window	Window Material Lite		Style	Style Dimensions Recessed		Brand/	Other			
		Pattern			Inset	Vendor				
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Plygem				
44	VINYL	1X1 / 1X1	SH	36X60	INSET & RECESSED	TBD				
45	VINYL	1X1	FIXED	48X24	INSET & RECESSED	TBD				
46	VINYL	1X1 / 1X1	SH	36X36	INSET & RECESSED	TBD				
47	VINYL	1X1 / 1X1	SH	36X36	INSET & RECESSED	TBD				
48	VINYL	1X1 / 1X1	SH	32X36	INSET & RECESSED	TBD				
48	VINYL	1X1 / 1X1	SH	36X16	INSET & RECESSED	TBD				
		·								